

Technical Bulletin

Bulletin Ref.:

UK-3-6-25

Date Issued:

30 September 2025

BULLETIN DETAILS

Product Group:	Quantum Powerchairs	Effective Date:	1 October 2025
Model(s) Affected:	Edge 3, Q6 Edge 2.0, Q6 Edge 2.0 HD, Edge 3 Stretto, 4Front 2, 4Front 3 HD, Q6 Edge HD		

Description of Changes/ Diviations:

This bulletin provides information regarding a change to the interface plates used on Quantum powerchairs that require lift. The interface plate design has been updated to reduce the overall weight while maintaining durability and functionality. The changeover will take place 1 October 2025.

This change applies to the following Quantum Rehab powerchairs with lift:

- Edge 3
- Edge 3 Stretto
- Q6 Edge 2.0
- Q6 Edge 2.0 HD
- Q6 Edge HD
- 4Front 2
- 4Front 2 HD

Important Note for Service Parts

- The old interface plate (now discontinued) covered all seat sizes.
- The new interface plates are seat size specific.
- When ordering a replacement interface plate as a separate part, ensure the correct plate is ordered for the seat size.
- Chairs ordered and built through Quantum will automatically be supplied with the correct interface plate.



OLD INTERFACE PLATES

NEW INTERFACE PLATES

Documentation Affected: Owner's Manual Order Form(s) Spec Sheets Other N/A

Link to new version of affected document:

For more detailed information, please contact your local designated Area Sales Manager.

NB: This Bulletin is for informational purposes only and DOES NOT replace the Specifications.

Pride Mobility Products Ltd.
32 Wedgwood Road, Bicester,
Oxfordshire, OX26 4UL

E: sales@quantumrehab.co.uk
T: +44 (0)1869 324600